

Tom L. Lewis
Mark M. Kovacich
Lewis, Slovak, & Kovacich, P.C.
P. O. Box 2325
Great Falls, MT 59403
(406) 761-5595

**IN THE UNITED STATES BANKRUPTCY COURT
FOR THE DISTRICT OF DELAWARE**

In re: : Chapter 11
W.R. GRACE & CO., et al : Case No. 01-01139 (JKF)
Debtors. : Jointly Administered
: Claim No. 00009667

**RESPONSE TO DEBTORS' FOURTEENTH OMNIBUS
OBJECTION TO CLAIMS (NON-SUBSTANTIVE)**

On behalf of claimant, Donald Munsel (Claim No. 00009667), his attorney, Tom L. Lewis of Lewis, Slovak & Kovacich, P.C., responds to Debtors' Fourteenth Omnibus Objection to Claims (Non-Substantive) as follows:

1. Claimant's claim relates to asbestos contamination from a W.R. Grace product in or on the property, to wit: asbestos-contaminated vermiculite from the W.R. Grace mine near Libby, Montana.
2. Claimant's claim is based upon the findings of the U.S. Environmental Protection Agency in its Administrative Record and supplement, test results, and other documentation, as well as information obtained from other sources, including but not limited to local and national news reports, articles and meetings.
3. Claimant consented to the production and release of supporting documentation, in the possession of the U.S. Environmental Protection Agency, to W.R. Grace and W.R. Grace's representatives at the time of submission of claim in March, 2003.

4. Claimant provided such supporting documentation as was available from the U.S. Environmental Protection Agency's Libby office, to W.R. Grace and W.R. Grace's representatives as an attachment to his Response to Debtors' Second Omnibus Objection to Claims (Non-Substantive), filed on August 8, 2003.

5. Claimant has attached a more legible copy of the supporting documentation previously provided as well as additional supporting documentation, which was not available at the time the proof of claim was filed nor at the time of his response to the Debtors' Second Omnibus Objection to Claims (Non-Substantive).

Respectfully submitted this 6 day of October, 2005.

Lewis, Slovak & Kovacich, P.C.

By: 
Tom L. Lewis
P.O. Box 2325
Great Falls, MT 59403
(Attorneys for Claimant)

CERTIFICATE OF SERVICE

I hereby certify that a true and legible copy of the foregoing Response to Debtors' Fourteenth Omnibus Objection to Claims (Non-Substantive) was served on the 6th day of October, 2005, by fax and by Federal Express courier, upon the following:

Co-Counsel for the Debtors:

Janet S. Baer
Kirkland & Ellis, LLP
200 East Randolph Drive
Chicago, IL 60601
fax 312-861-2200

Laura Davis Jones
Pachulski, Stang, Ziehl, Young,
Jones & Weintraub, P.C.
919 North Market Street, Suite 1700
P. O. Box 8705
Wilmington, DE 19899-8705
fax 302-652-4400

Counsel to the Official Committee of Unsecured Creditors:

Lewis Kruger
Stroock & Stroock & Lavan

Michael R. Lastowski
Duane, Morris & Heckscher, LLP

180 Maiden Lane
New York, NY 10038-4982
fax 212-806-6006

1100 N. Market Street, Suite 1200
Wilmington, DE 19801-1246
fax 302-657-4901

Counsel to the Official Committee of Property Damage Claimants:

Scott L. Baena
Bilzin, Sumberg, Dunn, Baena,
Price & Axelrod
First Union Financial Center
200 Southy Biscayne Boulevard, Suite 2500
Miami, FL 33131
fax 305-374-7593

Michael B. Joseph
Ferry & Joseph, P.A.
824 Market Street, Suite 904
P. O. Box 1351
Wilmington, DE 19899
fax 302-575-1714

Counsel to the Official Committee of Personal Injury Claimants:

Elihu Inselbuch
Caplin & Drysdale
399 Park Avenue, 36th Floor
New York, NY 10022
fax 212-644-6755

Marla Eskin
Campbell & Levine, LLC
800 N. King Street, Suite 300
Wilmington, DE 19801
fax 302-426-9947

Counsel to the Official Committee of Equity Holders:

Thomas M. Mayer
Kramer, Levin, Naftalis & Frankel, LLP
919 Third Avenue
New York, NY 10022
fax 212-715-8000

Teresa K.D. Currier
Klett, Rooney, Lieber & Schorling
1000 West Street, Suite 1410
P. O. Box 1397
Wilmington, DE 19899-1397
fax 302-552-4220

Counsel to the Future Claimants' Representative:

Richard W. Wyron
Swidler, Berlin, Shreff, Friedman LLP
3000 K Street, NW, Suite 300
Washington, DC 20007
fax 202-424-7643

John C. Phillips, Jr.
Phillips, Goldman & Spence, P.A.
1200 North Broom Street
Wilmington, DE 19806
302-655-4210

Office of the United States Trustee:

Office of the United States Trustee
Attention: David Klauder
844 N. King Street
Wilmington, DE 19801
fax 302-573-6497



Property Sample Datasheet

Property: 340 Autumn Rd

Sample ID	Sample Group	Location Description (Sub Location)	Matrix	Sample Date	PLM	
					Method	LA (%)
CS-14583-FG	Yard	Front yard	Surface soil	7/23/2003	PLM-VE	ND
CS-14584-C	Yard	Back yard	Surface soil	7/23/2003	PLM-Grav	NO
CS-14584-FG	Yard	Back yard	Surface soil	7/23/2003	PLM-VE	ND

n/62/02
90
BD- 003155
Ken

Soil samples collected (Date: _____)

LIBBY ASBESTOS PROJECT
Contaminant Screening Study
Primary Structure and Property Assessment Information Field Form (IFF)

Field Logbook No.: 100149 Page No.: 102 Site Visit Date: 11/62/02
Address: 370 Autumn Rd Structure Description: 2 trailer
Occupant: Rex Munsell Phone Number: 293-5101, 293-9351
Owner (if different than occupant): Rex Munsell Phone Number: 293-9398
Sampling Team: Paul Orman, Karen Berry (CDM)
Field Form Check Completed by (100% of forms): Marying Berry (CDM)
Screening Field Check Completed by (2% of forms): _____

Data Item	Value	Notes
HOUSE ATTRIBUTES		
Property Description	Residential <input checked="" type="checkbox"/> Industrial <input type="checkbox"/> Commercial <input type="checkbox"/>	
Surrounding Land Use	Residential <input checked="" type="checkbox"/> Industrial <input type="checkbox"/> Commercial <input type="checkbox"/> School <input type="checkbox"/> Mining <input type="checkbox"/> Other: <u>19783</u>	
Year of Construction	<u>19783</u> Unknown	
Square Footage	<u>980</u> 1080 <input type="checkbox"/> 11/04/02	
Construction Material	Wood frame <input checked="" type="checkbox"/> Masonry/Stone <input type="checkbox"/> Other: <u>Aluminum</u>	
Number of Floors Above Ground	<u>1</u> 2 3 Other: _____	
Number of Rooms Per Floor Above Ground	1: <u>6</u> 2: _____ 3: _____ Other: _____	
Basement	Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	
Heating Source	Wood/Coal <input checked="" type="checkbox"/> Electric <input type="checkbox"/> Propane/Gas <input type="checkbox"/> Other: _____	
Heat Distribution	Forced air <input checked="" type="checkbox"/> Radiant <input type="checkbox"/> Other: _____	

CSS INFORMATION FIELD FORM (continued)

Address: 390 Autumn RdBD# 003155

Data Item	Value	Notes
OCCUPANT INFORMATION		
Number of Adults/Employees	0 1 2 3 4 5-15 16-20 21-30 >30	2 in occ. structure 1-2,10 w/ flex rental
Number of Children	0 1 2 3 4 Other: _____	
Years at Location	<1 1-5 5-10 10-15 >15	
Was the residence/building remodeled?	Yes No	
	If yes,	
	When (years): <2 2-5 >5	
	Where: Attic Living Areas Garage Basement. Other: _____	
Has resident/business purchased any Libby vermiculite materials from W.R. Grace in the past?	Yes No	
	If yes,	
Has the property at this location been used for a for-profit enterprise of distributing, treating, storing, or disposing of Libby vermiculite?	Yes No	
	If yes,	
Are there any known areas of exposed vermiculite?	Yes No	
	If yes,	
	Where: Ceiling Walls Floors Attic Other: _____	

CSS INFORMATION FIELD FORM (continued)

Address: 390 Autumn Rd.BD# 003155

Data Item	Value	Notes
INDOOR ASSESSMENT		
Vermiculite Insulation Past or Present	Attic: Yes <input checked="" type="radio"/> No <input type="radio"/> NA Unknown Walls: Yes <input checked="" type="radio"/> No <input type="radio"/> NA Unknown Basement: Yes <input checked="" type="radio"/> No <input type="radio"/> NA Unknown Crawl Space: Yes <input checked="" type="radio"/> No <input type="radio"/> NA Unknown Other: _____	Visual confirmation of current presence or absence required for attic.
Evidence of Physical Damage?	Yes <input checked="" type="radio"/> No <input type="radio"/>	
Evidence of Water Damage?	Yes <input checked="" type="radio"/> No <input type="radio"/>	
OUTDOOR ASSESSMENT		
Libby Amphibole Sources Present	Garden: Yes <input checked="" type="radio"/> No <input type="radio"/> NA <u>Unknown</u> Yard: Yes <input checked="" type="radio"/> No <input type="radio"/> NA <u>Unknown</u> Stockpiles: Yes <input checked="" type="radio"/> No <input type="radio"/> NA <u>Unknown</u> Other: <u>Flowerbeds, 3/2/02</u>	<u>Snow cover</u> <u>yard's surface prevents</u> <u>inspection PS7-23-03</u>
Proximity to Other Properties with Potential Sources of Libby Amphiboles	Next door <u>Greenhouse</u> Within same block Other: _____ Unknown	

CSS INFORMATION FIELD FORM (continued)

Address: 390 Autumn RdBD# 003;55

Data Item	Value	Notes
EXPOSURE ASSESSMENT		
Type and Frequency of Activity Near Vermiculite Material - Indoor	Frequency: Once a day Once a week Once a month Once a year Not Applicable	Not Applicable applies when no vermiculite is present on the property.
	Duration of Contact: <1 hour 1-2 hours 2-4 hours >4 hours Not Applicable	
	Extent of Contact: Heavy Moderate Light Not Applicable	
Type and Frequency of Activity Near Vermiculite Material - Outdoor	Frequency: Once a day Once a week Once a month Once a year Not Applicable	Not Applicable applies when no vermiculite is present on the property.
	Duration of Contact: <1 hour 1-2 hours 2-4 hours >4 hours Not Applicable	
	Extent of Contact: Heavy Moderate Light Not Applicable	

CSS INFORMATION FIELD FORM (continued)

Address: 390 Autumn RdBD# 003155

Data Item	Value	Notes
CONTAMINANT SCREENING STUDY ASSESSMENT		
Occupant Information		
Is there any knowledge of former miners, close relative of miners, or any highly exposed persons living or visiting the property?	Yes Unknown	No
Is the resident, past or present, diagnosed with an asbestos related disease?	Yes PD 11/3/02 Unknown	No
		Don himself diagnosed with mesothelioma, Don's results screened, Don lives in a separate trailer. (BD# 003157)
Indoor Information		
Does the interior have Zonolite attic insulation?	Yes Unknown	No
Did the interior ever have Zonolite attic insulation?	Yes Unknown	No NA applies if attic currently has ZAI.
Are there vermiculite additives in any of the building materials?	Yes Unknown	No none observed
Outdoor Information		
Is there any evidence of primary source materials at or near the property?	Yes Unknown	No DS 7-23-03 Floor coverings found Surface presents Asperation
Could this have been tracked indoors or otherwise spread outdoors on the property?	Yes Unknown	No DS 7-23-03
Overall Assessment		
Are primary source materials present at the property?	Yes Unknown	No DS 7-23-03 Unknown
Where are primary source materials located?	Inside Both	Outside NA DS 7-23-03
ADDITIONAL INFORMATION	390 Autumn Rd consists of 2 trailers, 246 Autumn Rd is a vacant trailer between them. Rex Munsell lives in the trailer furthest to the north, Don Munsell lives in the trailer furthest to the south, 246 Autumn Rd is between those and vacant 1/2/02	

CSS INFORMATION FIELD FORM (continued)

Address: 390 + 241c, Autom Rd.

80# 805155


-803456-

11/02/02

FIELD DIAGRAM OF PROPERTY

Identify important features (i.e. drainage, trees, gardens, structures, flowerbeds, utility poles, known underground utilities, suspected Libby amphibole source areas, sample locations, etc). Include north arrow.

NOT TO SCALE



NOTE
S128

NOTES
SIZE & AGE A FOREST GARDEN
FLOWERBED
#340 MTH (CON UPTIME)

Automobile

BD- 003498
7-23-03

LIBBY ASBESTOS PROJECT
Contaminant Screening Study
Additional Information Field Form (AIFF)

Field Logbook No.: 100250 Page No.: 18 Site Visit Date: 7-23-03
 Address: 390 AUTUMN ROAD Structure Description: PUMP HOUSE
 Occupant: MR. + MRS. MUNSEL (DON) Phone Number: — 293-5101
 Owner (if different than occupant): REX MUNSEL Phone Number: 293-9398
 Business Name: N/A
 Sampling Team: COTTERY / SPELMAN 7-23-03
 Field Form Check Completed by (100% of forms):
 Screening Field Check Completed by (2% of forms):


Instructions: Pull existing residential file folder and original IFF; ensure past dust sampling FSDS, and soil sampling FSDS, are present. Conduct additional investigations as described below. If action item does not apply to the property, check item does not apply to this property.

Category and Action Trigger	Action	Notes
INDOOR SAMPLING/ATTIC INSPECTION		
Current presence of VCI - Unknown Answer to IFF question: Does the interior have VCI? = Unknown	<p>Current Status of VCI Determined:</p> <p><input type="checkbox"/> Yes, update existing IFF. If VCI is present, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> No, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input checked="" type="checkbox"/> Item does not apply to this property.</p>	7-23-03
Past presence of VCI - Yes Answer to IFF question: Did the interior ever have VCI? = Yes	<p>Remnants of Vermiculite Visible:</p> <p><input type="checkbox"/> Yes, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> No, collect dust samples in living space and attic per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> Unknown, attic cannot be accessed for visual inspection. Collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input checked="" type="checkbox"/> Item does not apply to this property.</p>	DS 7-23-03

7-23-03

CSS Additional IFF (Continued)

Address: 390 AUTUMN ROADBD# 003498

Category and Action Trigger	Action	Notes
Secondary Source Indications Answer to any IFF Secondary Source Indication questions (mining history, asbestos-related disease) = Yes	<input checked="" type="checkbox"/> Collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations. <input type="checkbox"/> Item does not apply to this property.	No ADDITIONAL INFO. IN PIFF
Vermiculite Present in Building Materials Answer to IFF question: Are there vermiculite additives in any of the building materials? = Yes	Condition of Vermiculite Containing Building Material: <input type="checkbox"/> Intact. No further action on this item required. <input type="checkbox"/> Friable, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations. <input checked="" type="checkbox"/> Item does not apply to this property.	D 7 23 3
Location dust samples NOT collected due to current presence of visible vermiculite (circle all that apply)	Basement Ground Floor Second Floor Attached Garage <u>None</u> Other: _____ <input type="checkbox"/> Item does not apply to this property.	Specific location of visible vermiculite: 122 S
OUTDOOR SAMPLING		
Visible vermiculite in large use area (Driveway or yard)	<input type="checkbox"/> Collect soil sample for each use area and add locations to existing property diagram. <input checked="" type="checkbox"/> Collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations. <input type="checkbox"/> Item does not apply to this property.	VISIBLE VERMICULITE IN YARD, DRIVEWAY
ADDITIONAL INFORMATION (Note any partial access or sample collection issues):		
		

BD- 003497

23-03

LIBBY ASBESTOS PROJECT
Contaminant Screening Study
Additional Information Field Form (AIFF)

Field Logbook No.: 100250 Page No.: 18 Site Visit Date: 7-23-03
 Address: 390 AUTUMN ROAD Structure Description: SHED
 Occupant: Mr. + Mrs. MUNSEL (Don) Phone Number: 293-5101
 Owner (if different than occupant): Rex MUNSEL Phone Number: 293-9398
 Business Name: N/A
 Sampling Team: Coffey / Spelman Mel J. J. B. 072503
 Field Form Check Completed by (100% of forms): _____
 Screening Field Check Completed by (2% of forms): _____

Instructions: Pull existing residential file folder and original IFF; ensure past dust sampling FSDS, and soil sampling FSDS, are present. Conduct additional investigations as described below. If action item does not apply to the property, check item does not apply to this property.

Category and Action Trigger	Action	Notes
INDOOR SAMPLING/ATTIC INSPECTION		
Current presence of VCI - Unknown Answer to IFF question: Does the interior have VCI? = Unknown	<p>Current Status of VCI Determined:</p> <p><input type="checkbox"/> Yes, update existing IFF. If VCI is present, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> No, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input checked="" type="checkbox"/> Item does not apply to this property.</p>	DS 7-23-03
Past presence of VCI - Yes Answer to IFF question: Did the interior ever have VCI? = Yes	<p>Remnants of Vermiculite Visible:</p> <p><input type="checkbox"/> Yes, collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> No, collect dust samples in living space and attic per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input type="checkbox"/> Unknown, attic cannot be accessed for visual inspection. Collect dust samples in living space per dust sampling protocol after reviewing existing dust sample locations.</p> <p><input checked="" type="checkbox"/> Item does not apply to this property.</p>	DS 7-23-03

DW
7-23-03